

Introduction of Measurements and Types of Error

- ✓ → JF/AE - ✓
- ✓ gate - 3-5 Marks
- ✓ ESE - 40 Marks
- ✓ ↪ Mains → 60 Marks - 80
- ✓ PSU →

Khemendra

Electrical Measurement

Direct Measurement :- Comparing unknown quantity with the known quantity

Indirect Measurement :- Either the current or voltage is converted to the mechanical deflecting system. So that by mean of pointer & scale reading can be taken.

Error :-

600 Rpm

A_T

True value

570 Rpm

A_m

Measured value.

Input = 600 rpm

fan

→ Output = 570

error = O/P - Input = 570 - 600 = -30

Static characteristic

Accuracy :- Closeness with an instrument reading approaches to true value

precision :- Measure of reproducibility

Sensitivity :- Ratio of change in output to change in input

$$\text{Sensitivity} \propto \frac{\theta}{I} \propto \frac{\text{Torque}}{\text{weight}} \rightarrow T/w \rightarrow \text{Ratio.}$$

Resolution : The small change in the input quantity which can be detected with its certainty.

Dead Zone : Largest change in the input quantity for which there is no output in the instrument.

Dead time : Time required by measuring system to begin to respond to a change in input.

Absolute Instrument

These instruments give the magnitude of quantity under measurement in terms of physical constants.

Ex → Tangent Galvanometer

→ Rayleigh current balance.

→

Secondary Instruments : Calibrated on the basis of Absolute Instrument.