

Hindbookcenter



Hind Book Center & Photostat

MADE EASY BPSC AE-2025 GENERAL ENGINEERING HANWRITTEN NOTES

- Colour Print Out
- Blackinwhite Print Out
- Spiral Binding,& Hard Binding
- Test Paper For IES GATE PSUs IAS, CAT
- All Notes Available & All Book Availabie
- Best Quaity Handwritten Classroom Notes & Study Materials
- IES GATE PSUs IAS CAT Other Competitive/Entrence Exams

Visit us:-www.hindbookcenter.com

**Courier Facility All Over India
(DTDC & INDIA POST)
Mob-9654451541**



Hindbookcenter



MADE EASY, IES MASTER, ACE ACADEMY, KREATRYX

**ESE, GATE, PSUs BEST QUALITY TOPPER HAND WRITTEN
NOTES MINIMUM PRICE AVAILABLE @ OUR WEBSITE**

- | | |
|--------------------------------|---------------------------|
| 1. ELECTRONICS ENGINEERING | 2. ELECTRICAL ENGINEERING |
| 3. MECHANICAL ENGINEERING | 4. CIVIL ENGINEERING |
| 5. INSTRUMENTATION ENGINEERING | 6. COMPUTER SCIENCE |

IES, GATE, PSU TEST SERIES AVAILABLE @ OUR WEBSITE

❖ IES –PRELIMS & MAINS

❖ GATE

➤ **NOTE;- ALL ENGINEERING BRANCHS**

➤ **ALL PSUs PREVIOUS YEAR QUESTION PAPER @ OUR WEBSITE**

PUBLICATIONS BOOKS -

**MADE EASY, IES MASTER, ACE ACADEMY, KREATRYX, GATE ACADEMY, ARIHANT, GK
RAKESH YADAV, KD CAMPUS, FOUNDATION, MC –GRAW HILL (TMH), PEARSON...OTHERS**

HEAVY DISCOUNTS BOOKS AVAILABLE @ OUR WEBSITE


Shop No.7/8 Saidulajab Market Neb Sarai More, Saket, New Delhi-30 9654353111	Shop No: 46 100 Futa M.G. Rd Near Made Easy Ghitorni, New Delhi-30	F518 Near Kali Maa Mandir Lado Sarai New Delhi-110030	F230, Lado Sarai New Delhi-110030
--	---	--	--------------------------------------

Website: www.hindbookcenter.com

Contact Us: 9654353111

Electrical machine

- ideal transformer
- Electromechanical energy conversion
- Dc motor, Dc generator
- Ac motor, generator



Right hand curl Rule → curl → represent direction of current

→ Faraday's law of electromagnetic induction. Thumb! - represent direction of flux.

→ The main task performed by transformer.

> Changing voltage and current levels.

> Maintain constant frequency, power and magnetizing flux.

→ Wound

→ Applications of transformer:-

>


generation → Transmission

↓
Distribution.

→ Construction of transformer:-

>

Core:-



> maximum flux

> minimum magnetizing current

> minimum core loss or iron loss

→ > High permeability and low reluctance

$\mu = \mu_0 \mu_r$
 Absolute permeability → Relative permeability
 For iron $\mu_r = 4000$

$R_l \text{ (Reluctance)} = \frac{l}{\mu A}$

$\text{Flux} = \frac{\text{MMF}}{\text{Reluctance}} = \frac{N \times I}{R_l}$

→ Si-steel core
(3%)

$\text{Core loss} = \text{Hysteresis loss} + \text{Eddy current loss}$


→ C. R. G. O (Si-steel)
(Cold rolled grain oriented Si-steel)

> windings:-

Copper wire

$I^2 R$ loss
ie
Copper loss.

L.V.
 ↓
 low voltage winding
 H.V.
 ↓
 High voltage winding



rms induced emf

$$E_1 = \sqrt{2} \pi f N_1 \phi_m$$

$$E_2 = \sqrt{2} \pi f N_2 \phi_m$$

$$\frac{E_2}{E_1} = \frac{\sqrt{2} \pi f N_2 \phi_m}{\sqrt{2} \pi f N_1 \phi_m} = \frac{N_2}{N_1}$$

$$\boxed{\frac{E_2}{E_1} = \frac{N_2}{N_1} = \frac{I_1}{I_2}} = k$$

Turn ratio
or
Transformation ratio

$$k = \frac{N_2}{N_1} = \frac{1}{3}$$

$$k = \frac{N_2}{N_1} = \frac{E_2}{E_1}$$

$\left. \begin{array}{l} N_1 > N_2 \\ E_1 > E_2 \\ I_1 < I_2 \end{array} \right\}$ step down transformer.

$$\Rightarrow \frac{1}{3} = \frac{E_2}{E_1} \Rightarrow E_2 = \frac{E_1}{3}$$

$\left. \begin{array}{l} N_1 < N_2 \\ E_1 < E_2 \\ I_1 > I_2 \end{array} \right\}$ step up transformer

> Transformer oil:-

It act as a insulation and as a coolant.

> Types of Xfer

→ Core type Xfer → It is suitable for high voltage and high power Application.


> Shell type Xfer

→ It is suitable for low voltage and low power application.

→ If Transformation ratio $\frac{N_2}{N_1} = \frac{E_2}{E_1} = k$

$k = 1:1$ → it is called isolation transformer.



Equivalent circuit of transformer



$\text{Resistance} \rightarrow R = \frac{\rho l}{A}$
 where ρ is Resistivity, l is length, and A is Area (Area or thickness).
 $\boxed{R \propto \frac{l}{A}}$



$X = 2\pi f L$
 primary equivalent circuit \rightarrow primary leakage impedance.
 secondary equivalent



Ideal transformer:-

→ No loss i.e.
no iron loss and no cu loss.
 $R_1 = 0, R_2' = 0$

For no iron loss $R_i = \infty$ i.e. open circuit.

> No leakage flux.

$$\text{Cu loss} = I^2 \cdot R$$

$$= I_1^2 \cdot R_1$$


$$\text{iron loss } P_i = \frac{E_1^2}{R_i}$$

in short circuit
 $R = 0$
 $V = I \cdot R$
 $V = 0$

Test of transformer:-

- > open circuit test
- > short circuit test
- > back to back test or Sumpner's test

→ open circuit test:
or
No load test



is used to determine
no load loss i.e. iron loss
or core loss, and
circuit parameters.

→ It is performed at
rated voltage.

$$I_1 = 100 \text{ Amp}$$

$$S = V_1 \cdot I_1$$

$$S = V_2 \cdot I_2$$




$$10 \times 10^3 = 100 \times I_2$$

$$I_2 = 100$$

$$S = V_1 \cdot I_1$$

$$= V_2 \cdot I_2$$

$$S = 10 \times 10^3 = 100 \times I_1$$



Volt-Ampere
kVA
mVA
Unit of Xfer.

→ short circuit test of transformer

in xfer

$I_0 \rightarrow$ no load current


\rightarrow 4 to 5% of full load current or rated current.

It is used to determine load loss i.e. Cu loss.

→ It is performed at rated current.

> back to back test or sumpner's test:-

\rightarrow It is used to determine temperature rise in the transformer.




Voltage regulation

what is the %age

Rise in terminal voltage from full load to no load.

It is called voltage regulation.

practically it is recommended (5 to 7%).



(voltage regulation)
$$V.R. = \frac{V_{NL} - V_{FL}}{V_{FL}}$$

$S = VI$

$P = VI \cos \phi$

$Q = VI \sin \phi$

True power

or Active power

Real power

Reactive power

\rightarrow using power factor improvement voltage regulation can be improved.

Power factor = $\frac{\cos \phi}{\sin \phi} = \frac{V}{I}$

$P \rightarrow$ watt or kW or MW

$Q \rightarrow$ VAR or kVAR or MVAR

$S \rightarrow$ VA, or kVA, or MVA

$\Delta Q \propto \Delta V$

Efficiency of Transformer:-

$$\eta = \frac{\text{power output}}{\text{power input}}$$

Power input = power o/p + losses

$$\eta = \frac{\text{Power o/p}}{\text{Power o/p} + \text{losses}}$$

Most of the time power transformer operates on its rated condition.
 So efficiency of transformer is maximum at rated load or near around rated load.

Condition for maximum efficiency

η_{\max}

Iron loss

$$P_i = \frac{E_1^2}{R_i} = \frac{V_1^2}{R_i}$$

it is voltage dependent loss. so it is constant loss.

★ Iron loss = copper loss

or

constant loss

or

No load loss = variable loss or load loss

→ Copper loss = $I^2 \cdot R$

it is depends on load current

so it is load loss or variable loss.

★ In general efficiency of transformer is around (90 to 95 %).

Q:-

For the construction of the core of the transformer the material used should have _____ permeability and _____ Reluctance.

- (a) High, High
- (b) Low, Low
- ☒ (c) High, Low
- (d) Low, High

Reluctance

$$\left\{ R_l = \frac{l}{\mu A} \right\}$$

Q:-

A transformer is said to be a step up transformer when.

- ☒ (a) Voltage transformation ratio is greater than 1
- (b) Voltage transformation ratio is zero.
- (c) Voltage transformation ratio is less than 1
- (d) Voltage transformation ratio is equal to 1.

Transformation ratio




→ $\left(N_2 > N_1 \right)$ $K = \frac{N_2}{N_1} = \frac{V_2}{V_1}$
 $K > 1$ i.e. $\frac{N_2}{N_1} = \frac{V_2}{V_1} > 1$

→ Types of transformer



> Core type

Shell type

Core type transformer:



Voltage rating \propto insulation



1 turn voltage = 10V/t




→ In core type transformer

Low voltage winding is kept inside. So as to reduce the cost of insulation.

→ It is suitable for High voltage and high power application.

→ shell type transformer:-



→ It is suitable for low voltage and low power application.

→ Core loss or Iron loss in transformer

$$P_c = \text{Hysteresis loss} + \text{eddy current loss.}$$

Hysteresis loss P_h :-

$$P_h = k_h B_m^{1.6} \times f \rightarrow \text{Frequency}$$

\downarrow
 Constant

\searrow
 $B_m \rightarrow$ Peak flux density

Eddy current loss:


$$P_e = k_e B_m^2 f^2$$

\downarrow
 Constant


$B_m =$ Peak flux density
 $f =$ Frequency.

Three phase transformer :-


↪ 3 → 1 ϕ unit.



→ Star winding.



Delta winding.



→ 3 ϕ transformer connections

- 0° Connection and 180° Connection \leftarrow $>$ $Y-Y$ transformer (star-star transformer)
 0° Connection and 180° Connection \leftarrow $>$ $\Delta-\Delta$ transformer (Delta-Delta transformer)
 $\pm 30^\circ$ Connection \leftarrow $>$ $Y-\Delta$ transformer (star-Delta " Π ")
 $\pm 30^\circ$ Connection \leftarrow $>$ $\Delta-Y$ transformer (Delta-star " Π ")
 0° Connection and 180° Connection \leftarrow $>$ Δ -zigzag Y (Delta-zigzag Y)
 $\pm 30^\circ$ Connection \leftarrow $>$ Y -zigzag Y (star-zigzag Y)

→ operative parallel operation

Transformer-1

$Y-Y$
 $\Delta-\Delta$
 $\Delta-Y$
 $Y-\Delta$

Transformer-2

$Y-Y, \Delta\Delta, \Delta$ zigzag Y
 $\Delta-\Delta, Y-Y, \Delta$ zigzag Y
 $\Delta-Y, Y-\Delta, Y$ -zigzag Y
 $Y-\Delta, \Delta Y, Y$ zigzag Y

→ $\Delta-\Delta$ transformer


$S = V_1 I_1 = \frac{V_2}{\sqrt{3}} I_2$
 $10 \times 10^3 = \frac{100}{\sqrt{3}} \times I_1$
 $I_1 = 100A$
 $10 \times 10^3 = \frac{100}{\sqrt{3}} \times I_2$
 $I_2 = 10A$

$Y \downarrow$ → star with neutral ground
 Y → star with neutral unground.

→ In star connected winding if neutral is grounded cost of insulation get reduced, so star connected winding is used for high voltage or low current application.



→ Delta (Δ) connected winding is used for low voltage or high current application.

→ The additional advantage of Δ transformer is that it can be operated as an open delta if one of the 3 ϕ unit fail to supply.



> parallel operation of transformer

DC Source



Circulating Current.


$$I_c = \frac{10-8}{R_s} = \frac{10-8}{.01}$$

$$I_c = \frac{2}{.01} = 200A$$

Condition for parallel operation

- > magnitude of voltage should be same
- > polarity should be same.

$$I_c = \frac{10-10}{R_s} = 0$$



$$I_c = \frac{10 - (-10)}{R_s}$$

Q:-


Which of the following three phase transformer combination can be successfully run in parallel.



- (a) star-star and Delta-star
- (b) Delta-Delta and Delta-star
- ☒ (c) Delta-star and Delta-star
- (d) Star-delta and Delta-Delta

Q:- Which is to shortcircuited on performing Short circuit test on a transformer.

- (a) Low voltage side
- (b) primary side
- (c) High voltage side
- (d) secondary side.




Q:- What happens if a dc supply is applied to a transformer's primary.

$\frac{V_2}{V_1} = k$ For dc inductor
behave as a short
circuit

$$V_2 = k V_1$$

burn out





$$V_L = L \frac{di}{dt}$$

$$V_L = 0$$

DC machine


Hard magnetic (ie wider B-H loop)
[tungsten steel]




exact view
of rotor and stator
are cylindrical

stator

→ Top







→ In dc m/c:

Stator → Field winding
Rotor → Armature winding

Field winding:- To produce main flux or to establish main field.

Armature winding:- → In which induced emf → (generator Action).

→ on which torque is produced (Motor action)



C_1, C_2 → Commutator segment
(semi circular shape)

Carbon brushes B_1, B_2 (stationary)

Induced emf in DC M/c:-

$$E = \frac{P \phi Z N}{60 A}$$

P = number of poles


ϕ = Avg flux.

Z = number of conductors

N = speed in rpm (revolution per minute)

A = number of parallel path.

Armature winding pattern



For Wave winding (High voltage low current application)

no. of parallel path
 $A=2$

For Lap winding:-

(High current low voltage application)

$A=P$

Types of DC M/c

> Separately excited dc machine

> self excited dc machine

shunt

series

compound.

Excitation:-

To flow the current in the field winding to establish the working flux.
or
produce